WowWee CHiP Robot Dog Smart Watch Battery Replacement

Replacing the battery inside of the WowWee CHiP Robot Dog Smart Watch.

Written By: Joseph Dantes

This document was generated on 2020-11-28 07:12:48 AM (MST).

🔧 TOOLS:

- Phillips #0 Screwdriver (1)
- Soldering Iron (1)

Step 1 — Smart Watch Battery

- Place the Smart Watch on its back or side so that the full watch band is visible.

Step 2

- Remove the wrist strap by gently pulling the band off of the plastic pegs on the back of the watch.

Step 3

- Remove the four screws in the back of the watch using a Phillips #0 screwdriver.

Step 4

- Gently pull off the back side of the watch component.

This document was generated on 2020-11-28 07:12:48 AM (MST).

© iFixit — CC BY-NC-SA   www.iFixit.com   Page 4 of 5

Step 5

- Pull the battery and motherboard component out.

To reassemble your device, follow these instructions in reverse order.