M6013 Capacitor Meter Teardown

Teardown of M6013 Capacitor Meter

Written By: Ted Hsueh

This document was generated on 2020-11-19 07:14:31 PM (MST).

© iFixit — CC BY-NC-SA   www.iFixit.com   Page 1 of 5

INTRODUCTION

How to take apart the M6013 Capacitor Meter

🔧 TOOLS:

- Phillips #0 Screwdriver (1)

This document was generated on 2020-11-19 07:14:31 PM (MST).

www.iFixit.com

Step 1 — Removing Battery

- Remove the circled screw

- Remove battery case and batteries

Step 2 — Removing Case

- Remove circled screws

- Pull case apart

⚠ Watch out for buttons, they will fall out easily.

This document was generated on 2020-11-19 07:14:31 PM (MST).

© iFixit — CC BY-NC-SA

www.iFixit.com

Page 3 of 5

Step 3 — Remove Circuit Board

- Remove circled screws

⚠ Be careful when removing the circuit board, the battery cable is still connected.

- Unsolder the square locations either on the circuit board or the case to fully remove the circuit board

Step 4 — Microprocessor

- Location of microprocessor

Step 5 — Remove Display

- Remove the cable connector

- Remove Display

To reassemble your device, follow these instructions in reverse order.