



Written By: Connor Talbot



INTRODUCTION

If your Acer Aspire S3-391-6046 ultrabook is overheating, it might be a problem with the fan assembly. This is a guide for how to remove and replace it.



TOOLS:

- [Phillips #1 Screwdriver](#) (1)
 - [Tweezers](#) (1)
-

Step 1 — Back Cover




- Place laptop upside down.

Step 2




- Remove the twelve 5mm screws with a Phillips #1 screwdriver.

Step 3



- Lift cover upwards away from you.

Step 4 — Fan



- Unscrew the three screws with a Phillips #0 screwdriver.

Step 5



- Use either your hands or the tweezers to gently peel back the tape.

Step 6



⚠ Do not pull anything by the wires.

- Use the tweezers to gently pull the small black plug out.
- After the plug is out, you should be able to pull the fan assembly out.

To reassemble your device, follow these instructions in reverse order.