

Escort Passport 9500IX Back Panel Replacement

How to replace a Escort Passport 9500IX back panel.

Written By: Kennedy Morales



This document was generated on 2020-11-28 07:12:30 AM (MST).

INTRODUCTION

To keep your device protected, make sure that the back panel of your device is crack free. If your radar's back panel has a really bad crack, follow these steps to replace it.



TOOLS:

- Spudger (1)
- Phillips #1 Screwdriver (1)

Step 1 — Back Panel



Remove the three 1.2 mm Phillips
#1 screws on the back of the device.

Step 2



 Pry off the back panel of the radar using the nylon spudger.

To reassemble your device, follow these instructions in reverse order.