



# LG VX5500 Audio Port Replacement

If no sound comes from headphones that are...

Written By: Kurt Beske



# INTRODUCTION

If no sound comes from headphones that are plugged into the audio port, you may need to install a new one. Follow this guide to diagnose and resolve the issue.

## TOOLS:

[Phillips #00 Screwdriver](#) (1)

[iFixit Opening Tool](#) (1)

[Soldering Workstation](#) (1)

[Tweezers](#) (1)

## Step 1 — Battery



- Remove the battery cover by placing your thumb on the small ridge near the top of the phone back and push downward, exposing the battery.
- ⓘ Our device did not come with a battery cover so it is not shown here.
- Remove the battery using your finger to pry it out of the battery housing.

## Step 2 — Audio Port




- Remove the (2) rubber screw covers located near the hinge of the phone using [tweezers](#) or a thumb tack.
- Unscrew the (4) 3.6mm screws using a #00 Phillip's head screw driver.

## Step 3



- Carefully pry off the phone's backing using a plastic opening tool.
- Slip the tool into the crack between the keypad (front panel) and the back panel.
- Slide the tool along the sides of the phone to detach the tabs holding the backing on.

## Step 4



- Locate the audio port; this is what it should look like.
- The audio port is mounted and connected at 6 points. Check the integrity of these connections.
- ⓘ If any of the connections are dislodged or the audio port is damaged, desolder the port and install a new one.

To reassemble your device, follow these instructions in reverse order.