


# Oculus Rift Development Kit 2 Headset Motherboard Replacement

If the device is not working properly this...

Written By: Adam



#### **INTRODUCTION**

If the device is not working properly this could be due to a broken headset motherboard. Common causes for motherboard failures include being exposed to static shock, overheating, or component failure.

## 🖌 TOOLS:

Phillips #0 Screwdriver (1) Tweezers (1) iFixit Opening Tool (1)

#### Step 1 — Eye Relief Adjustment Screw



- Remove front cover plate.
- Unplug the USB and HDMI cables from the Oculus Rift DK2.

#### Step 2



• Remove the four 3/8" Phillips #0 screws from the inner portion of the headset.



• With the screws removed, gently pull the headband frame apart from the headset.


#### Step 4 — Remove Lens



• With the Oculus facing up, twist the right lens clockwise and lift it out. Repeat for the left lens twisting counterclockwise instead.

## Step 3

#### Step 5 — Headset Motherboard



• Using <u>tweezers</u>, carefully lift the four rubber plugs as shown. They are a bit snug and you may need to jiggle them free with the tweezers.

## Step 6



 Remove the four 3/8" screws attaching the eyewear enclosure to the front casing.

A Read the next step before removing the faceplate!




• Carefully separate the faceplate and the cover. Gently rest the cover plate on top of the faceplate as shown in the pictures.

 $\Delta$  Do not use excessive force when separating these two pieces. There is a delicate ribbon cable connected to each.

## Step 7

#### Step 8




- Gently pull out the small side tabs on the ribbon cable connector as shown to release the cable.
- Push the tabs away from you, with the headset oriented as pictured. Carefully slide the ribbon cable out.
- (i) The headset should now be two separate pieces.

#### Step 9



• Unscrew the three 1/4" Phillips #00 screws as pictured and use the tweezers to lift them out.

#### Step 10



• Lift the tape and gently pry up the video data ribbon cable using the plastic opening tool as shown.

## Step 11



• Gently pry back the motherboard clips to release the motherboard. The motherboard should now lift free.

To reassemble your device, follow these instructions in reverse order.